

Brake Chamber damage caused by improper chassis stacking



## Contributing AFFECT:

- Driver stated air system for brakes was leaking.
- Mechanic investigated origin of leak.
- Touched brake chamber with hand.
- Due to broken retaining ring bolt (result of stacking), diaphragm became projectile and struck the mechanic.
- Connected airlines prevented serious injury.

